

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 1

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Approvals:

Process Plan: *[Signature]*

Date: 11-07-14

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3272

Rev B

100

0.00



DOCUMENT CONTROL

to

DC

Memo

0.00

Document Control

Photocopy bluefile and type labels as per PPP D350-591-311 CHG001

5 u l o s t r e

JJ Car BG 11-8-18

110

0.00



Large Fab

Large Fab

Memo

0.00

Large Fab

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272

A/R ☐ Aluminum Rod

3-Grind End Plate flush

*1114703
1117884*

11-08-12 5
11-08-13 5

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 2

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120

QC9- Inspect visual per QSI004- Fusion Welds

0.00



QC

Memo

0.00

Quality Control

5 0 221/08/15

130

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

Sulox 15



140

Chemical Conversion Coat per QSI005 4.1

0.00



HandFinish

Memo

0.00

Hand Finishing

H/A 11.08.15

x5 0

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 3

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

150

QC3- Inspect Part Finish

0.00



QC

Memo

0.00

Quality Control

EPB/08/16 (5)

180

Large Fab

0.00



Large Fab

Memo

0.00

Large Fab

1-Assemble Leg Assembly as per Dwg D3272.

2-Leave one rivet out until welding is complete.

3-Bevel Aft end for welding

4-Inspect for foreign object as per QSI 024

5-Weld Aft End Plate as per QSI 004 & Dwg D3272

A/R ☐ Aluminum Rod ☒ 1114703

6-Grind End Plate flush

7-Install last rivet as per Dwg.

KE / *11-08-16* (5) *11-08-17*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 4

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

190

QC10- Inspect visual per QSI004- ground welds

0.00



QC

Memo

0.00

Quality Control

8 u/a/22

200

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

8 u/a/22

x5

LH

210

Chemical Conversion Coat per QSI005 4.1

0.00



HandFinish

Memo

0.00

Hand Finishing

SX Jm-11/08/22
LH

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 5

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

220

White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum

0.00



Powdercoat

Powder Coating

Memo

START TIME: 3:45
OVEN TEMPERATURE: 320 OF
FINISH TIME: 4:15

0.00

SXD M/L 11/08/22

230

Wing Walk as per dwg QSI005 4.4 Batch

0.00



HandFinish

Hand Finishing

Memo

M118313

0.00

SXD M/L 11/08/23

240

QC3- Inspect Part Finish

0.00



QC

Quality Control

Memo

0.00

S BL 11-8-23.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 6

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
250	Pick Kit	0.00							
Packaging	Memo	0.00							
Packaging									
260	QC4- 100% Inspect kits for completeness	0.00							
QC	Memo	0.00							
Quality Control									
270	Packaging	0.00							
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPPD350-591-311								
	Location: <u>RA1</u>								

11/8/23 SPS

8/16/24

KS
LH

Reub

1/8/25 SPS

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71959

Thursday, July 14, 2011 10:34:17 AM



Page 7

Item ID: D350-591-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011 Start Qty: 5.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 5.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

280

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

n. 8/25/11

C21108/25

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries




Thursday, July 14, 2011 10:34:23 AM

Page 1

[illegible]

Required Qty: 5.00

Comments: IPP Rev:A 04.03.22 New issue KJ/RF
IPP Rev:B 07-06-09 Added D3272-1 JLM
IPP C returned to CHG001 for Eurocopter, ref NCR08-082 LL verified by:EC
IPP Rev:D fixe route seq in bom DD 10.04.28 verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3272-1  Step		Manufactured	No			110	Each	8.0000	1	5		11.08.12	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA	<u>371961</u>			8		5			
					71395			8					
D3067-1  End Plate		Manufactured	No			110	Each	105.0000	1	5		11.08.12	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA				84					
					67582			2					
					70700			82					
				WA016				21					
					<u>68214</u>			21		5			
D3219-1  Plate		Manufactured	No			110	Each	96.0000	2	10		11.08.12	
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				WA017				96					
					<u>68338</u>			96		10			

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 10:34:23 AM

Page 2

Work Order ID: 71959

Parent Item: D350-591-311

Parent Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 5.00

Required Qty: 5.00

D3066-1 Manufactured No

180 Each

143.0000 2 10



Spacer



Ae 11-08-16

Location

Loc Qty

Loc Code

WA

143

69738

29

70699

114

(40)

MS20600-AD4W4 Purchased No

180 Each

1,888.000 16 80



Rivets



Ae 11-08-16

Location

Loc Qty

Loc Code

ST321

1883

116188

59

117364

1000

117601

200

117885

224

118267

400

WA018

5

116712

5

(x80)

D3065-041 Manufactured No

180 Each

8.0000 1 5



Step Leg Assembly Hi



Ae 11/08/16

Location

Loc Qty

Loc Code

WA

8

66149

0

69740

8

B70778 (x5)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 10:34:24 AM

Page 3

Work Order ID: 71959

Parent Item: D350-591-311

Parent Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 5.00

Required Qty: 5.00

D3067-1

Manufactured No

180 Each

105.0000

1

5



End Plate



11-08-18

Location

Loc Qty

Loc Code

WA

84

67582

2

70700

82

WA016

21

68214

21

AN3-35A

Purchased No

250 Each

109.0000

2

10



Bolt



10

Location

Loc Qty

Loc Code

ST353

109

117619

19

117794

50

118112

40

D3235-1

Manufactured No

250 Each

113.0000

2

10



Mounting Lug



10

Location

Loc Qty

Loc Code

ST471

113

68292

13

69837

100

D3278-041

Manufactured No

250 Each

44.0000

1

10



Support Assembly



10

5

Location

Loc Qty

Loc Code

ST471

44

68957

4

69741

40

Thursday, July 14, 2011 10:34:24 AM

Shop Packet Print

Page 3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 10:34:24 AM

Page 4

Work Order ID: 71959

Parent Item: D350-591-311

Parent Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 5.00

Required Qty: 5.00

AN960JD416 NAS1149D0463J Purchased No

250 Each

0.0000

16 80

Washer

AN960JD516 NAS1149D0563J Purchased No

250 Each

0.0000

4 20

Washer

AN5-36A Purchased No

250 Each

93.0000

2

Bolt

Location

Loc Qty

Loc Code

ST341

93

117794

43

118012

50

D2618 Manufactured No

250 Each

177.0000

2

Bushing

Location

Loc Qty

Loc Code

ST019

177

70702

73

71600

104

D2230-3 Manufactured No

250 Each

218.0000

4

Lug

Location

Loc Qty

Loc Code

ST

94

70694

94

ST476

4

53881

4

ST480

120

70973

120

Thursday, July 14, 2011 10:34:24 AM

Shop Packet Print

Page 4

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 10:34:24 AM

Page 5

Work Order ID: 71959

Parent Item: D350-591-311

Parent Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 5.00

Required Qty: 5.00

D2856-400

Manufactured No

250 f

82.7896 1.2



Abraison Strip



6

Location

Loc Qty

Loc Code

ST403

82.12

68076

82.12

ST409

0.6696

63735

0.6696

*** cut (2) at 7.20" (D2856-400-720) ***

MS21042L3

Purchased No

250 Each

1,666.000 2



Nut



10

Location

Loc Qty

Loc Code

ST300

1666

116549

28

117441

800

117601

400

117885

438

AN4-13A

Purchased No

250 Each

666.0000 8



Bolt



40

M118350 11/8/2011

Location

Loc Qty

Loc Code

ST357

666

117962

72

118078

594

Thursday, July 14, 2011 10:34:25 AM

Shop Packet Print

Page 5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 10:34:25 AM

Page 6

Work Order ID: 71959

Parent Item: D350-591-311

Parent Item Name: Heli-Access-Step, Long LH

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 5.00

Required Qty: 5.00

MS21042L5

Purchased

No

250

Each

1,388.000

2

10



Nut

Location

Loc Qty

Loc Code

ST300

1388

116105

5

116548

199

117441

498

117591

100

117611

90

118179

496

MS21042L4

Purchased

No

250

Each

4,043.000

8

40



Nut

Location

Loc Qty

Loc Code

ST300

4043

117441

1796

117601

747

117885

1500

AN960JD10

NAS1149D0363J

Purchased

No

250

Each

0.0000

4

20



Washer

1118077

102

Thursday, July 14, 2011 10:34:25 AM

Shop Packet Print

Page 6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

DART

DESIGN <i>GP</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>H</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED07.06.04 *H*

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *71959*
07-11-07-14

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____



Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN	DRAWN BY	DART AEROSPACE LTD HAMKESBURY, ONTARIO, CANADA
CHECKED <i>ce</i>	APPROVED <i>[Signature]</i>	REV. B
DATE 07.05.18	TITLE STEP ASSEMBLY, HI LONG	SHEET 2 OF 3
		SCALE 1:20



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>GP</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20




DETAIL C

B D3272-1 STEP

(MAKE FROM D2622-120 STEP EXTRUSION)

65816 g/m



DRILL $\phi 0.128$ (#30) FROM JIG ON BOTH SIDES OF D3272-1 EXTRUSION TO MATCH D3065-041 HOLE PATTERN

DETAIL C
(SCALE 1:5)

RELEASED

07.06.04 *[Signature]*

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Qty -211	Qty -212	Qty -213	Qty -214	Qty -215	Qty -216	Qty -311	Qty -312	Part Number	Description
X								D350-591-211	Heli-Access-Step™, Long Step – High Skid, LH
	X							D350-591-212	Heli-Access-Step™, Long Step – High Skid, RH
		X						D350-591-213	Heli-Access-Step™, Short Step – High Skid, LH
			X					D350-591-214	Heli-Access-Step™, Short Step – High Skid, RH
				X				D350-591-215	Heli-Access-Step™, Short Step – Low Skid, LH
					X			D350-591-216	Heli-Access-Step™, Short Step – Low Skid, RH
						X		D350-591-311	Heli-Access-Step™, Long Step – High Skid, LH
							X	D350-591-312	Heli-Access-Step™, Long Step – High Skid, RH
1								D3070-041	STEP ASSEMBLY (HIGH-LONG, LH)
	1							D3070-042	STEP ASSEMBLY (HIGH-LONG, RH)
		1						D3078-041	STEP ASSEMBLY (HIGH-SHORT, LH)
			1					D3078-042	STEP ASSEMBLY (HIGH-SHORT, RH)
				1				D3168-041	STEP ASSEMBLY (LOW-SHORT, LH)
					1			D3168-042	STEP ASSEMBLY (LOW-SHORT, RH)
						1		D3272-041	STEP ASSEMBLY (HIGH-LONG, LH)
							1	D3272-042	STEP ASSEMBLY (HIGH-LONG, RH)
4	4							D2182B035	RUBBER CUSHION
		2	2	2	2			D2230-1	MOUNTING LUG
		2	2	2	2	4	4	D2230-3	MOUNTING LUG
8	8							D2274	RADIUS BLOCK
						2	2	D2618	BUSHING
4	4	4	4	4	4			D2732-030	CUSHION
2	2	1	1	1	1	2	2	D2856-400-720	ABRASION STRIP
2	2							D3064-1	CLAMP
1	1							D3079-041	SUPPORT ASSEMBLY
4	4							D3080-1	CLAMP
						2	2	D3235-1	MOUNTING LUG
						1	1	D3278-041	SUPPORT ASSEMBLY
2	2	2	2	2	2	2	2	AN3-35A	BOLT
10	10	2	2	2	2			AN4-11A	BOLT
		4	4	4	4	8	8	AN4-13A	BOLT
						2	2	AN5-36A	BOLT
4	4	4	4	4	4	4	4	AN960JD10	WASHER
20	20	12	12	12	12	16	16	AN960JD416	WASHER
						4	4	AN960JD516	WASHER
2	2	2	2	2	2	2	2	MS21042L3	NUT
10	10	6	6	6	6	8	8	MS21042L4	NUT
						2	2	MS21042L5	NUT
						1	1	*DSI 9410-011	STEP MODIFICATION KIT

*DSI 9410-011 Step Modification Kits are provided with all D350-591-311 and D350-591-312 Steps. This kit is provided as an option for the installer and is therefore **NOT REQUIRED** to complete the installation of the D350-591-311 or D350-591-312 Steps. Refer to Figure 21 for installation of the DSI 9410-011 Kit.